


# Instruction of Installing Zero-Injection Port on Single-Phase 5KW Inverter


- 一. To avoid any electric shock, cut off all power of the inverter before you commence the installation.
- 1. Cover your working platform with anti-static foam and put the inverter face down on it. Using a cross-screwdriver to unscrew all 14 screws in anti-clockwise.




- 2. Then put the inverter face up and lift the cover board up. Attention, you should not lift it more than 20 centimeters in case breaking cables.



3. Disconnecting all cables in cover board and take down the cover board. Taking down the seal in CON port and install a zero-injection port on it.



4. Re-connecting all cables.



5. Put the inverter face-down and secure all screws. Do not crush any cable on the edge.

